4600

profile

4600 137 gr/m




bending

radius


R 10 (1012) R 10 (1015) R>80 (1018)




Mounting ceiling



ceiling mounting with ceiling mounting clamp 2650(incl. washer), with wood screw 261.



ceiling mounting 4600 with ceiling mounting clamp 2650 + washer, before (a) and after (b) fastening the ceiling mounting clamp



when mounting a curved rail, place a ceiling mounting clamp before as well as after the curve

G-Standard

